# Versions and History

Wireless intruder alarm panels

TELETEK

| BRAVO | | | |
|---|---|---|---|
| **Current Version** | **Date** | **Version** | **Changes** |
| →→→ | 6.12.2021 | SW 6.02 / HW 1.91 | Changes required due to new processor version |
| | 9.9.2021 | SW 6.01 / HW 1.91 | 1. AC lost messsage filtration added<br>2. Stay Arm event coming from Bravo KBD is now recorded correctly into the panel's log<br>3. Manager cannot delete his own code. It can only be edited |
| | 12.1.2021 | SW 6.0 / HW 1.91 | 1. Bravo KBD support<br>2. Adding wireless devices via ProsTE software<br>3. Bravo MIO module support - wired zones support |
| | 23.2.2018 | SW 5.01 / HW 1.91 | User cannot edit parameters through Ajax WEB.Only manager and engineer users can edit parameters! |
| | 7.12.2016 | SW 5.0 / HW 1.91 | 1. Encrypted wireless communication with the devices<br>2. Support of one-way remote controls (RC-11, RC-21 and RC-41)<br>3. Walk Test is now activated through engineer menu(device enrollment menu)<br>4. Controlling a PGM of the Bravo MOUT module by means of Bravo RC<br>5. Panel LEDs Test<br>6. Changes in accordance with the requirements of 50131-1: 8.3.8.2 and 50131-1: 8.4.2 |
| | 6.10.2016 | SW 4.03 / HW 1.91 | HW: Increased RF stability in noisy environments. |
| | 13.9.2016 | SW 4.03 / HW 1.90 | Stability improvements |
| | 11.2.2016 | SW 4.02 / HW 1.90 | 1. Event reporting improvements<br>2. Slot 1 and 2 are both primery when MOUT module is set to work as PGMs<br>3. Clock reset in case of power lost<br>4. SMS sending |
| | 10.2.2016 | SW 4.01 / HW 1.90 | 1. Battery recharge is improved<br>2. 3rd slot added<br>3. Micro USB connector is now used<br>4. New GPRS antena connector<br>5. External adapter is changed |
| | 20.11.2015 | SW 4.01 / HW 1.50 | Bugfix |
| | 14.10.2015 | SW 4.00 / HW 1.50 | New:<br>- Area Account code could be from 4 to 6 digits<br>- Factory reset indication changes<br>Changes:<br>- APN settings filed is now up to 30 symbols<br>- ZONE_ALARM_RESTORE gets write to log in case of alarm cicle expire |
| | 25.3.2015 | SW 3.00 / HW 1.50 | New:<br>- Daylight Saving Time<br>- Bravo RC "*" button - different function on each device<br>- Sqwauk signal for external sirens (wireless & wired)<br>- All wireless devices can be saved in ProsTE (*.TDF) file<br>- Support for new Bravo SR300<br>- Support for new Bravo PSTN VD<br>- Added 2 more phone numbers in PSTN/PSTN VD<br>- Bravo MOUT supports wired siren<br>- PGM names<br>- New Icons' set<br>Changes:<br>- Water Leak alarm without siren sound<br>- PSTN test procedure LED lightning<br>- Power turns off & on after Firmware Update<br>- Engineer is not allowed to Arm, StayArm, Disarm, Bypass and PGM On/Off. |
| | 25.3.2015 | SW 2.09 / HW 1.50 | Fixed battery missing detection at 4037mV (from 4100mV). |
| | 2.2.2015 | SW 2.08 / HW 1.50 | Added second account code for Ajax GPRS module. Account codes now are 4/6 digits. Improved tamper event algorithm. |
| | 23.1.2015 | SW 2.07 / HW 1.50 | Buttons are chaged with silicone keypad & buttons. |
| | 20.1.2015 | SW 2.07 / HW 1.50 | Replaced capacitor (2,2uF - 12030060) |
| | 16.12.2014 | SW 2.07 / HW 1.40 | New functionality for Bravo MOUT module. Improvement in Bravo GPRS and postponed messages. |
| | 14.11.2014 | SW 2.06 / HW 1.40 | Added Zone Name programmed remotely by ProsTE, AjaxWEB. |
| | 17.10.2014 | SW 2.05 / HW 1.40 | Mainboard redisign and EMI improvements. |
| | 18.6.2014 | SW 2.05 / HW 1.20 | Added 2*Manager and 6*User Codes for remote access |
| | 14.12.2013 | SW 2.04 / HW 1.20 | Initial version of SW & HW |

Last Update 14.09.2022

**All rights reserved by Teletek Electronics**
**For internal use only**